



CANADIAN SPORT PARACHUTING ASSOCIATION
ASSOCIATION CANADIENNE DE PARACHUTISME SPORTIF

TECHNICAL BULLETIN #112

TECHNICAL BULLETIN # 112

SPECTRA RESERVE RIP CORDS

UPT has found that some spectra reserve ripcords may have been coated with the wrong solution mix, which may result in a harder pull. The affected rip cords and batch numbers are available on their website. The numbers can be found on the white tag attached to the spectra ripcord line. Refer to [Service Bulletin 2015-01](#).

Action to be taken: If you find that your ripcord is one of the affected ones it must be changed out at the next pack cycle. There are procedures in the Service Bulletin as to what must be done to treat the ripcord until the reserve comes due for repack. Follow all instruction in accordance with UPT Service Bulletin 2015-01

Who can do the modification/Repair: Rigger A or higher.

Robert MacNeill – Chair
Technical and Safety Committee
24 Jun 2015

OUR JOB, THEIR SAFETY, OUR AIM, PERFECTION.

AFFILIATE: AERO CLUB OF CANADA – FÉDÉRATION AÉRONAUTIQUE INTERNATIONALE