



CANADIAN SPORT PARACHUTING ASSOCIATION
ASSOCIATION CANADIENNE DU PARACHUTISME SPORTIF

TECHNICAL BULLETIN #106

TECHNICAL BULLETIN # 106

Item #1 United Parachute Technologies Service Bulletin #20121106

UPT has instructed the support washer to be removed from the bungee staging loop.

Action to be taken: Remove the support washer at the next repack cycle and tie a double overhand knot instead.

Who can carry out the inspection: Inspection and correction may be made by any Rigger A or B, or a Rigger with a foreign equivalent.

Inspection And Replace Procedures

The procedures are laid out on the UPT website.

[http://unitedparachutetechnologies.com/PDF/Support/Product Service Bulletins/PSB-2012116-Removal-of-support-washer-from-the-Reserve-Staging-Loop.pdf](http://unitedparachutetechnologies.com/PDF/Support/Product%20Service%20Bulletins/PSB-2012116-Removal-of-support-washer-from-the-Reserve-Staging-Loop.pdf)

Robert MacNeill – Chair
Technical and Safety Committee
21 March, 2013

OUR JOB, THEIR SAFETY, OUR AIM, PERFECTION.

AFFILIATE: AERO CLUB OF CANADA – FÉDÉRATION AÉRONAUTIQUE INTERNATIONALE