



CANADIAN SPORT PARACHUTING ASSOCIATION
ASSOCIATION CANADIENNE DU PARACHUTISME SPORTIF

TECHNICAL BULLETIN #108

TECHNICAL BULLETIN # 108

Item #1 Vigil II Waterproof Inspection

Compliance MANDATORY

Waterproof inspection of Vigil II multimode (civilian model only). After a Vigil II has been immersed in water it must be returned to the manufacturer for inspection. IAW PSB-9. See attached website for further information.

http://www.pia.com/piapubs/ServiceBulletins/PSB9_2013_06_14.pdf

Item #2 14 Hour Automatic Shutdown

Compliance Advisory

The Vigil II will automatically shut down after 14 hours, If traveling between drop zones ensure the Vigil II is shut down and restarted for each drop zone, IAW manufacture's instructions. For further information review PSB-10 for full procedures.

<http://www.vigil.aero/wp-content/uploads/PSB-10-2013-06-14-.pdf>

Robert MacNeill – Chair
Technical and Safety Committee
24 May, 2013

OUR JOB, THEIR SAFETY, OUR AIM, PERFECTION.

AFFILIATE: AERO CLUB OF CANADA – FÉDÉRATION AÉRONAUTIQUE INTERNATIONALE