



CANADIAN SPORT PARACHUTING ASSOCIATION
ASSOCIATION CANADIENNE DE PARACHUTISME SPORTIF

TECHNICAL BULLETIN #113

TECHNICAL BULLETIN # 113

VIGIL CUTTERS MANUFACTURED MARCH 2015 - JULY 2015

An investigation into a report of a severed closing loop resulted in the locating of an abrasive edge in the cutter unit. Cutters manufactured in the March to July 2015 window are affected. Affected serial numbers are listed on the Vigil site at www.vigil.aero. [PSB 01-2015](#).

Action to be taken: Check the hologram placed on the cutter. If your cutter's hologram number does not appear on List A or List B from the PSB 01-2015, no further action is required. If the hologram number does appear follow the instructions listed in PSB 01-2015.

Who can do the modification/Repair: Rigger A or higher.

Robert MacNeill – Chair Technical and Safety Committee
15 Dec 2015

OUR JOB, THEIR SAFETY, OUR AIM, PERFECTION.

AFFILIATE: AERO CLUB OF CANADA - FÉDÉRATION AÉRONAUTIQUE INTERNATIONALE