



CANADIAN SPORT PARACHUTING ASSOCIATION
ASSOCIATION CANADIENNE DU PARACHUTISME SPORTIF

TECHNICAL BULLETIN #79

TECHNICAL BULLETIN #79

Item #1 – Argus Service Bulletin

Aviacom SA, manufacturers of the Argus Automatic Activation Device, have issued Service Bulletin AMM290506/1 following the ground firing of one of their units.

It has been discovered a last minute software update in the May batch of units caused this problem.

Erring on the side of caution, Aviacom stopped shipment of units manufactured in May and have recalled 40 units having the serial numbers displayed below. Dealers and owners have been notified. These units will be upgraded and returned as soon as received at the factory.

Serial numbers

0506021101325 0506021101332 0506021101349 0506021101356 0506021101363
0506021101387 0506021101394 0506021101400 0506021101417 0506021101714
0506021101721 0506021101738 0506021101745 0506021101752 0506021101769
0506021101776 0506021101783 0506021101806 0506021101813 0506021101820
0506021101851 0506021101875 0506021101899 0506021101905 0506021101912
0506021101929 0506021101936 0506021101943 0506021101950 0506021101967
0506021101974 0506021101981 0506021101998 0506021102001 0506021102018
0506021102025 0506021102032 0506021102056 0506021102063 0506021102070

FMI: call +32 2 785 02 80 or email info@argus-aad.com

Barry McAuley – Chair
Technical & Safety Committee
May 2006