



CANADIAN SPORT PARACHUTING ASSOCIATION ASSOCIATION CANADIENNE DU PARACHUTISME SPORTIF

TECHNICAL BULLETIN #86

TECHNICAL BULLETIN #86

Item #1 - ICON Grommets

Aerodyne Research, manufacturers of the popular ICON series of harness/container systems, has issued precautionary service bulletin #SB271107 that recommends grommet inspection on all affected systems.

Affected systems are all ICON harness/container systems, part number P120, manufactured after and including 01September 2007.

A field report revealed that there were some damaged grommets on an ICON container. The ICON was inspected by Aerodyne and it was determined that the grommets had been damaged by the grommet press. The damage can be seen on the inside of the grommet. Grommets need to be inspected to ensure correct and flush seating.

Although this could be an isolated incident, as a precaution Aerodyne is recommending all grommets on all ICON container systems identified above be inspected.

Further information can be obtained by contacting:

Aerodyne Research
12649 Race Track Road
Tampa, FL 33626
1 813 891-6300
www.flyaerodyne.com

Item #2 – Rigger Forum

An informal Rigger's Forum will be held in Winnipeg on the evening of Saturday, January 19th, 2008. The T&SC has scheduled one of their regular meeting in Winnipeg and invites Riggers, current and not so current, to an informal evening of discussion on topics of interest.

Venue for the forum is: Hilton Suites Winnipeg Airport
1800 Wellington Ave.
Winnipeg, MB
19:00 – 22:00

Barry McAuley – Chair
Technical & Safety Committee
December 2007



Canadian
Heritage

Patrimoine
canadien

Sport Canada

AFFILIATE: AERO CLUB OF CANADA • FÉDÉRATION AÉRONAUTIQUE INTERNATIONALE