



CANADIAN SPORT PARACHUTING ASSOCIATION  
ASSOCIATION CANADIENNE DU PARACHUTISME SPORTIF

## TECHNICAL BULLETIN #105

### TECHNICAL BULLETIN # 105

#### **Item #1 Sun Path Service Bulletin # SPSB008**

Sun Path has issued a service bulletin stating that there is an issue with some of the release cable lengths and that an immediate inspection should be made of all main canopy release handles (part # JP068-1) delivered with the systems with the date of manufacturing of January 2009 through present (Feb 2013).

**Action to be taken:** All equipment with the manufacturing dates as stated above must be inspected IAW manufacture's instructions.

**Who can carry out the inspection:** Inspection and correction may be made by any Rigger A or B, or a Rigger with a foreign equivalent.

#### **Inspection Procedures**

Inspection procedures are available from the Sun Path website at:

<http://www.sunpath.com/support/bulletins.html>

Robert MacNeill – Chair  
Technical and Safety Committee  
March, 2013

## **OUR JOB, THEIR SAFETY, OUR AIM, PERFECTION.**

**AFFILIATE: AERO CLUB OF CANADA – FÉDÉRATION AÉRONAUTIQUE INTERNATIONALE**