



CANADIAN SPORT PARACHUTING ASSOCIATION ASSOCIATION CANADIENNE DU PARACHUTISME SPORTIF

TECHNICAL BULLETIN #92

TECHNICAL BULLETIN #92

Item #1 - Javelin Odyssey Immediate Inspection

Sun Path Products Inc. have issued Service Bulletin SPSB005 that affects all sport Javelin Odyssey Harness/ Container Systems with Hip Ring or 4 Ring main lift web, with a date of manufacture between September 2008 and December 2008.

It was brought to their attention that the hip ring on JH101-3 (Hip ring only) and JH101-4 (4-ring) main lift webs may have been struck by the machine needle used for installing the 5 cord harness stitching. A needle strike on the hip ring may cause damage to the Type 12 buffer, 5 cord stitching and possibly the Type 7 webbing itself. As a precaution, immediate mandatory inspection of the hip rigs is required for all systems with a date of manufacture between **September 2008 and December 2008**.

If damage is found, the harness/container system will need to be returned to Sun Path Products.

To view this seven page bulletin, contact Sun Path at: <http://www.sunpath.com>

Item #2 – Rigger Gatherings

It has been suggested that riggers from local geographical areas should be getting together occasionally to discuss rigging issues that may crop up from time to time. This would not need to be a formal event of any nature—just a gathering of interested parties to voice opinions or offer solutions to help resolve problems that can arise in day to day rigging. Be the first to organize a gathering in your area!

Barry McAuley – Chair
Technical & Safety Committee
February 2009



Canadian
Heritage

Patrimoine
canadien

Sport Canada

AFFILIATE: AERO CLUB OF CANADA • FÉDÉRATION AÉRONAUTIQUE INTERNATIONALE