



CANADIAN SPORT PARACHUTING ASSOCIATION
ASSOCIATION CANADIENNE DU PARACHUTISME SPORTIF

TECHNICAL BULLETIN #107

TECHNICAL BULLETIN # 107

Item #1 United Parachute Technologies Service Bulletin #20132005

Retractable Y-strap mod.

Action to be taken: All affected harnesses are to have the modification complete no later than Dec 1, 2013

Who can do the modification: Rigger B or foreign equivalent.

Inspection And Replace Procedures

The procedures are laid out on the UPT website.

<http://goo.gl/SgVda>

Robert MacNeill – Chair
Technical and Safety Committee
24 May, 2013

OUR JOB, THEIR SAFETY, OUR AIM, PERFECTION.

